



Service Report

Ticket No.:		Service Order No.:	2100009249	Responsible Technician:	Karim Darahim	Date:	12.08.2026
Customer reference:		OHC_9xRMQ+4xScala FACQ/Van Luyck J.					
Customer:				Site details:			
Name:	FACQ NV			Name:	Facq Showroom Namur		
Contact Person:	Julie Van Luyck			Contact Person:			
Phone:	+3227198553			Phone:			
Mobile:				Mobile:			
Address:	Leuvensesteenweg 561			Address:	Rue d'Enhaive 188		
Postal Code:	1930			Postal Code:	5100		
City:	ZAVENTEM			City:	Namur		
Email:	Julie.VanLuyck@facq.be			Email:			
Equipment:							
Service ID:	94379283192110021330						
Application Type:	Récupération d'eau de pluie			Pump Type:	Scala 3-45		
Pump location:	Local Technique						
Control Panel location:							
Description:	SCALA1 System 3-45 1x230V						
Product number (complete product):	99976872			Motor type:			
Equipment number:	304224521			Customer reference:			
Production (year):	2407			Motor number:			
Pump/motor configuration:							
Warranty:	Yes: ☐ No: ☒						
Symptom:	Inspection Annuelle						
Description of used spare part(s) and kits							
Product Number	Description			Quantity	Unit		
Time and Travel Schedule							
Standard Working Hours	Out of hours/holiday	24/7 Service	Travel time	Kilometers			
1	0	0	0.5	80			

Remarks/conclusion/further recommendations

12.08.2026 | Karim Darahim
Type: Scala 1 System 3-45
Model: 92947788
P5: 2407

Groupe vérifié fonctionnel aussi bien sûr l'eau de pluie que sur l'eau de ville.
Test d'arrêt OK.
Pas d'alarme dans le log.

Handover

Customer representative		Signature
Date and time:	12.08.2026	
Name (print):	Biot	

Attachments

Trend .JPEG

